

Michael Muskepo
851 Brightwaters Blvd NE
St. Petersburg, FL 33704

July 19th, 2019

To whom it may concern,

I was involved in an accident with Mrs. C. Schafer on Friday, July 12th, 2019 around 1:35 PM in Saint Petersburg Florida. I was driving a red Mazda CX3 (around 33 miles/hour in a zone with a 35 miles/hour speed limit) in the right lane on 4th Street N going north. My stepbrother and stepsister were also in the car with me. We were almost at 27th Ave N when the other driver came onto 4th Street N from the left side of the road and proceeded to drive straight in the left lane in the same direction that I was driving. She then suddenly turned right into the City Produce parking lot (without using a turn signal), crossing the right lane in which I was driving. I braked as hard as I could, but still lightly hit her car around the rear light.

Direct after the accident I asked about her well-being, and she let us know she was ok. About 30 minutes later a police officer came, and she also told him that she had no injuries.

I was not under the influence of any drugs, alcohol, or medication; I was not distracted by my phone, radio, or passengers; and I was not driving above the speed limit or swerving across the road.

The damage to my car is estimated by Northwest Collision Center in St. Petersburg to be \$1,290.02.

I hereby declare that the details are correct as far as I know.

Michael Muskepo,



Tatyana Jongsma, (parent)



Rozemarijn jongsma,
Born 6/11/1998





Tjerk J. Jongsma,
Born 6/30/2000



Route of the cars

See the print of Google Maps with the route of our cars and the pictures taken by me of the road where this accident happened. Attached are also the pictures of the damage to both cars and the estimate for the damage on my car.



Pictures of the Road




The red car at the stop sign from which the other driver came. On the other side of the street City Produce is located where the driver pulled into.



This is the view from the other side of the street. I was driving on the right most lane just like the red truck seen above. The other driver came from the same place the blue Honda is standing. The City Produce parking lot can be seen on the right.

Damage To My Car:



Damage To Other Driver's Car:



My Driver's License:



Her Driver's License:





NORTHWEST COLLISION CENTER LLC

QUALITY WORKMANSHIP LIFETIME WARRANTY
SINCE 1959

3301 TYRONE BLVD, SAINT PETERSBURG, FL
33710

Phone: (727) 347-8945

FAX: (727) 344-1357

Workfile ID: 32e64045
PartsShare: 5tW73g
Federal ID: 26-1586142
License Number: mv-95785

Preliminary Estimate

Customer: Muskepo, Michael

Written By: RICHARD SNIPES

Insured: Muskepo, Michael
Type of Loss: Collision
Point of Impact: 12 Front

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
Muskepo, Michael
(727) 238-1189 Day

Inspection Location:
NORTHWEST COLLISION CENTER LLC
3301 TYRONE BLVD
SAINT PETERSBURG, FL 33710
Repair Facility
(727) 347-8945 Business

Insurance Company:
AUTO-OWNERS

VEHICLE

2018 MAZD 3 5-Door Grand Touring Automatic 4D H/B 4-2.5L Gasoline Gasoline Direct Injection SOUL RED

VIN: 3MZBN1M34JM241172	Interior Color:	Mileage In:	Vehicle Out:
License:	Exterior Color: SOUL RED	Mileage Out:	
State: FL	Production Date:	Condition: Good	Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Tinted Glass
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel
Climate Control
Backup Camera

RADIO

AM Radio
FM Radio
Stereo
Search/Seek

Auxiliary Audio Connection
Premium Radio
Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device
Blind Spot Detection

ROOF

Electric Glass Sunroof

SEATS

Bucket Seats

Reclining/Lounge Seats
Leather Seats
Heated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Three Stage Paint

OTHER

Fog Lamps
Traction Control
Stability Control
Rear Spoiler
Signal Integrated Mirrors
Xenon Headlamps

Preliminary Estimate

Customer: Muskepo, Michael

2018 MAZD 3 5-Door Grand Touring Automatic 4D H/B 4-2.5L Gasoline Gasoline Direct Injection SOUL RED

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER					
2		O/H bumper assy				3.2	
3	*	Rpr Bumper cover				<u>3.0</u>	2.8
4		Add for Three Stage					2.0
5	Repl	Bumper cover clip	B45A56146A	1	1.70		
6	Repl	Bumper cover grommet	GHP9500Z5	2	1.96		
7	Refn	Tow brkt cover					0.2
8		Add for Three Stage					0.1
9		GRILLE					
10	**	Repl A/M CAPA Grille black	BADH50712C	1	93.00	1.1	
11	*	R&I Sight shield				Incl.	
12		Repl LT Molding	BANE507K1	1	67.46	Incl.	
13		Repl Grille cover red	BANE50033A62	1	134.99	Incl.	0.3
14		Add for Three Stage					0.1
15		Repl Grille cover clip	TK2150355	4	9.40		
16		Repl Grille cover rivet	S51S51833	4	11.52		
17	#	Repl FLEX ADDITIVE		1	12.00		
18	#	HAZARDOUS WASTE		1	5.00		
19	#	COVER CAR OVERSPRAY		1			0.2
20	#	Color tint / color match		1			0.5
21	#	Rpr Color sand and buff					1.0
SUBTOTALS					337.03	7.3	7.2

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			337.03
Body Labor	7.3 hrs @	\$ 46.00 /hr	335.80
Paint Labor	7.2 hrs @	\$ 46.00 /hr	331.20
Paint Supplies	7.2 hrs @	\$ 28.00 /hr	201.60
Subtotal			1,205.63
Sales Tax	Tier 1 \$ 1,205.63 @	7.0000 %	84.39
Grand Total			1,290.02
INSURANCE PAY			1,290.02